



Date: Friday, 30/11/2007 9:58:17 AM
 User: Linda Lacelle

Process Sheet

Customer	: CC-DAR01 Dart Aerospace Ltd.	Drawing Name	: SCRAP
Job Number	: 36076		
Estimate Number	: 10804		
P.O. Number	: <i>N/A</i>	Part Number	: D350591121
This Issue	: 30/11/2007	Drawing Number	: NCR 263
S.O. No.	: <i>N/A</i>	Project Number	: <i>N/A</i>
Prsht Rev.	: NC	Drawing Revision	: <i>N/A</i>
First Issue	: <i>N/A</i>	Material	: <i>N/A</i>
Type	: LARGE FAB ASSY	Due Date	: 07/12/2007
Previous Run	: 00015	Qty:	1 Um: Each
Written By	: 		
Checked & Approved By	: 		
Comment	:		

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
----------------	------------------------------	----------------------

1.0

QC

QUALITY CONTROL



Comment: QUALITY CONTROL

REMOVE FROM STOCK:

1 X D350-591-121 B 31405 *7/12/13*
 SCRAP PER NCR 263
 IDENTIFY ANY PARTS THAT ARE TO BE
 RETURNED TO STOCK:

MS21042L4 M103914-X3 ✓
MS21042L3 M102658-X2 ✓
AN960JD416 M102929-X4 ✓
AN960JD10 M103641-X4 ✓
AN4-13A M103363-X3 ✓
AN3-37A M102337-X2 ✓
D2856-400-720 B29850-X1 ✓
D2230-3 B30273-X1 ✓
D2230-1 B30155-X1 ✓
AS 7/12/13

2.0

D350591121

Heli-Access-Step LH



Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s)
 Heli-Access-Step LH *7/12/13*

3.0

QC21

FINAL INSPECTION/W/O RELEASE

Comment: FINAL INSPECTION/W/O RELEASE *7/12/13*

Job Completion

*U 7/12/13*